



DETAIL A




NOTES:

1. Mill Outer Bolt Lug as shown.
2. Δ Locate from the bolt head surface.
3. Δ Locate from the inner lug surface.
4. All 3 decimal dimensions $\pm .005$.
5. Break all sharp corners.
6. Brush alodine per MIL-C-5541.




Indicate from the inner lug surface. Do Not Mill.



Indicate from bolt head surface. Do Not Mill.

Figure 1



Left Hand Repair Bracket Shown
 Right Hand Bracket is Mirror Image of Left Hand

Figure 2